

IR Scan Results



These images were taken on **8/9/2005** at **1:00:12 PM**

File Name	Pic029.jpg
-----------	------------

Infrared Image Information	Ambient Temperature	-
Temperature Rise (AR01 - AR02)		10.5 °F
Reference Temperature (AR02)		90.0°F
Point of Concern Temp. (AR01)		100.4°F

<u>Infrared Image Information</u>	
Location	Front Entrance
Problem	Moisture Saturation
Condition	Serious
Comments	May cause Rotting

Unprotected dry wood often wicks water like an oil lamp wicks oil

<u>IR Technician Information</u>			
IR Technician	Olen C. Sawyer	Certification #	Level II # 12514
Phone Number	Toll Free 1-866-412-2368		Cell 828-230-0314