



IR Scan Results



These images were taken on **11/1/2005** at **6:26:59 PM**

File Name	lr_0170.jpg
------------------	-------------

<u>Infrared Image Information</u>	Ambient Temperature -
--	------------------------------

Temperature Rise (AR01 - AR02)	60.9 °F
Reference Temperature (AR02)	69°F
Point of Concern Temp. (AR01)	130°F

<u>Infrared Image Information</u>
--

Location	2
Problem	MOV arrester
Severity	Critical
Comment's	

Improperly torqued connections is the major cause of these type problems. Few bother to check the manufacturing specifications on new equipment. The results from these failures often range from personal injury to costly physical damage at the least

<u>IR Technician Information</u>			
IR Technician	Olen C. Sawyer	Certification #	Level II #12514
Phone Number	Toll Free 1-866-412-2368		Cell 828-230-0314