


## IR Scan Results



These images were taken on **11/9/2005** at **10:29:14 AM**

File Name | Ir\_0186.jpg

### Infrared Image Information

Ambient Temperature -

<b>Temperature Rise ( AR01 - AR02)</b>	<b>11.2 °F</b>
<b>Reference Temperature (AR02)</b>	54°F
<b>Point of Concern Temp. (AR01)</b>	65°F

### Infrared Image Information

<b>Location</b>	2
<b>Problem</b>	Improperly installed U.G. Terminator
<b>Severity</b>	Critical
<b>Comment's</b>	

Failed Underground Terminators are often excessive when it comes to time and labor paid to correct . Not to mention customer dissatisfaction . Quality and Reliability are Hugh in todaysUtility Industry.

### IR Technician Information

<b>IR Technician</b>	Olen C. Sawyer	<b>Certification #</b>	Level II # 12514
<b>Phone Number</b>	<b>Toll Free 1-866-412-2368</b>		<b>Cell 828-230-0314</b>