


## IR Scan Results



These images were taken on **8/9/2005** at **1:13:39 PM**

File Name Pic045.jpg

<u>Infrared Image Information</u>	<b>Ambient Temperature</b>
<b>Temperature Rise ( AR01 - AR02)</b>	<b>7.9 °F</b>
<b>Reference Temperature (AR02)</b>	72.7°F
<b>Point of Concern Temp. (AR01)</b>	80.6°F

<u>Infrared Image Information</u>	
<b>Location</b>	1
<b>Problem</b>	Insulation
<b>Condition</b>	Minor
<b>Comments</b>	minor corrections

Insulation was disturbed during fixtuer replacement . Over an extended period of time can be a very costly problem when the solution is only penny's

<u>IR Technician Information</u>			
<b>IR Technician</b>	Olen C. Sawyer	<b>Certification #</b>	Level II # 12514
<b>Phone Number</b>	Toll Free 1-866-412-2368		Cell 828-230-0314