



IR Scan Results



These images were taken on **11/30/2005** at **11:46:38 AM**

File Name	lr_0062.jpg
------------------	-------------

<u>Infrared Image Information</u>	Ambient Temperature -
Temperature Rise (AR01 - AR02)	85.8 °F
Reference Temperature (AR02)	114.7°F
Point of Concern Temp. (AR01)	200.6°F

<u>Infrared Image Information</u>	
Location	Process Dryer #1
Problem	Program Processer component overheating
Severity	Critical (Process Shutdown)
Comment's	

Unexpected process interruption is often caused by electronic component failure.

<u>IR Technician Information</u>			
IR Technician	Olen C. Sawyer	Certification #	Level II # 12514
Phone Number	Toll Free 1-866-412-2368		Cell 828-230-0314