



## IR Scan Results



These images were taken on **1/23/2005** at **1:54:46 PM**

<b>File Name</b>	lr_0146.jpg
------------------	-------------

<b><u>Infrared Image Information</u></b>	<b>Ambient Temperature</b> -
<b>Temperature Rise ( AR01 - AR02)</b>	<b>74.5 °F</b>
<b>Reference Temperature (AR02)</b>	54.5°F
<b>Point of Concern Temp. (AR01)</b>	129.0°F

<b><u>Infrared Image Information</u></b>	
<b>Location</b>	2
<b>Problem</b>	Air Break switch connections failing
<b>Severity</b>	Critical
<b>Comment's</b>	

Unexpected failure of this type equipment can be devastating to Hospitals , Manufacturing processes or critical customers

<b><u>IR Technician Information</u></b>			
<b>IR Technician</b>	Olen C. Sawyer	<b>Certification #</b>	Level II # 12514
<b>Phone Number</b>	<b>Toll Free 1-866-412-2368</b>		<b>Cell 828-230-0314</b>