



IR Scan Results



These images were taken on **11/8/2005** at **11:35:29 AM**

File Name | Ir_0178.jpg

<u>Infrared Image Information</u>	Ambient Temperature -
Temperature Rise (AR01 - AR02)	6.8 °F
Reference Temperature (AR02)	63°F
Point of Concern Temp. (AR01)	70°F

<u>Infrared Image Information</u>	
Location	Industrial Park anywhere
Problem	Improperly installed fuse
Severity	Critical
Comment's	

These issues can be completely avoided with a good infrared predictive maintenance program and possible avoid numerous compensation claims

<u>IR Technician Information</u>			
IR Technician	Olen C. Sawyer	Certification #	Level II # 12514
Phone Number	Toll Free 1-866-412-2368		Cell 828-230-0314