


## IR Scan Results



These images were taken on **8/9/2005** at **1:04:15 PM**

File Name: **Pic033.jpg**

<b><u>Infrared Image Information</u></b>	<b>Ambient Temperature</b> -
<b>Temperature Rise ( AR01 - AR02)</b>	<b>15.7 °F</b>
<b>Reference Temperature (AR02)</b>	73.4°F
<b>Point of Concern Temp. (AR01)</b>	89.2°F

<b><u>Infrared Image Information</u></b>	
<b>Location</b>	Upstairs Bedroom
<b>Problem</b>	premature wall outlet failure
<b>Condition</b>	Critical
<b>Comments</b>	Electrical problem

*Electrical problems range from minor to Fatal if ignored . With an anomaly of only 15.7 degrees this is a very serious problem*

<b><u>IR Technician Information</u></b>			
<b>IR Technician</b>	Olen C. Sawyer	<b>Certification #</b>	Level II # 12514
<b>Phone Number</b>	<b>Toll Free 1-866-412-2368</b>		<b>Cell 828-230-0314</b>