

IR Scan Results



These images were taken on **1/14/2005** at **12:26:46 PM**

File Name | Ir_0135.jpg

<u>Infrared Image Information</u>	Ambient Temperature
Temperature Rise (AR01 - AR02)	16.4 °F
Reference Temperature (AR02)	27.5°F
Point of Concern Temp. (AR01)	44.0°F

<u>Infrared Image Information</u>	
Location	Front Windows
Problem	Loss of Vacume Seal
Condition	Minor
Comments	Windows should be replaced

Loss of Vacume seal on thermalpayne glass. Undetectable to the eye

<u>IR Technician Information</u>			
IR Technician	Olen C. Sawyer	Certification #	Level II # 12514
Phone Number	Toll Free 1-866-412-2368		Cell 828-230-0314