



These images were taken on 10/13/2005 at 4:48:54 PM

File Name lr_0106.jpg

IR Information

Temperature Rise	197.8 °F	Condition	Critical
Reference Temperature	201°F		
Point of Concern Temp.	398°F		

Location/Equipment Information

Equipment	Padmount
Point of Concern	Alu 2 bolt Spade
Location of Point of Concern	Unknown at this point
Reference Address	Unknown

Comments **Corrections should be made as soon as possible**

IR Technician Information

IR Technician	Olen C. Sawyer Johnny Jordan	Certification #	Level II # 12514
Phone Number	1-866-412-2368 Cell 828-230-0314		